© 2023 York Flashings



HEAD CONDITION





JAMB CONDITION





SILL CONDITION



YORK Flashings™

AS A MANUFACTURER OF CONSTRUCTION MATERIALS, YORK MANUFACTURING, DOES NOT ASSUME RESPONSIBILITY FOR ERRORS IN DESIGN OR ENGINEERING. ARCHITECT OR OWNERS REPRESENTATIVE MUST VERIFY SUITABILITY OF DETAILS.

TYPE B- CURTAIN WALL BRICK OPTION

AirSill™ Flashing Receiver